






NOTE 1: STRINGERS ARE EPOXIED OR SOLDERED IN PLACE. NOTE 2: THIS IS THE FRAME, TO PROVIDE GOOD CONTACT ON THE RECEIVER AN EPOXY WEDGE IS MADE TO FILL THE GAP

















0.063

Π