



NOTE 1: FLAT IS OPTIONAL  
 NOTE 2: LEAD SCREW SOURCED FROM MCMaster CARR PART #99030A704

<small>ALL ATTEMPTS HAVE BEEN MADE TO PRESENT AN ACCURATE DRAWING BASED ON THE SOURCE MATERIAL. USE SOURCE MATERIAL TO PROOF THIS DRAWING PRIOR TO USE. READ THE TECHNICAL NOTES ON THIS DRAWING PRIOR TO USE.</small> <small>IF ERRORS IN THIS DRAWING ARE DISCOVERED EMAIL JAYANDREW338@GMAIL.COM.</small>		<b>TITLE:</b> <b>Y &amp; Z Axis Lead Screw</b>	
<b>MATERIAL</b> 1018	<b>SIZE</b> <b>B</b>	3D PRINTER Cube	<b>REV</b> <b>N/A</b>
<small>DO NOT SCALE DRAWING</small> <small>IF YOU LIKE WHAT YOU SEE HELP SUPPORT US DONATE VIA PAYPAL</small>	<b>SCALE:</b> 1:2	<b>WEIGHT:</b>	SHEET 1 OF 1