



NOTE 1: GUIDE ROD SHOULD BE HARDENED TO ALLOW FOR USE WITH LINEAR BEARINGS
 NOTE 2: COUNTER SINK OPTIONAL, MAY HELP WITH TAPPING 1/4-20 THREADS

<small>ALL ATTEMPTS HAVE BEEN MADE TO PRESENT AN ACCURATE DRAWING BASED ON THE SOURCE MATERIAL. USE SOURCE MATERIAL TO PROOF THIS DRAWING PRIOR TO USE. READ THE TECHNICAL NOTES ON THIS DRAWING PRIOR TO USE.</small> <small>IF ERRORS IN THIS DRAWING ARE DISCOVERED EMAIL JAYANDREW338@GMAIL.COM.</small> <small>MATERIAL</small>		TITLE: <h2>Z-Axis Guide Rod</h2>	
Case Hardened Steel	SIZE B	3D PRINTER Cube	REV N/A
<small>DO NOT SCALE DRAWING</small> <small>IF YOU LIKE WHAT YOU SEE HELP SUPPORT US DONATE VIA PAYPAL</small>	SCALE: 1:2	WEIGHT:	SHEET 1 OF 1